

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID: 39098	2. Page 1 of 3	3. Generator Phone: 214-789-1627	4. Manifest Tracking Number: 002888838 FLE	
5. Generator's Name and Mailing Address: US EPA Region 6 - CES Environmental Site 1445 Ross Ave. STE 1200 Dallas, TX 75202-2733 214-789-1627		Generator's Site Address (if different than mailing address): US EPA Region 6 - CES Environmental Site 4904 Griggs Road Houston, TX 77021				
6. Transporter 1 Company Name: Environmental Evolutions		U.S. EPA ID Number: 88021				
7. Transporter 2 Company Name:		U.S. EPA ID Number: TXR000076018				
8. Designated Facility Name and Site Address: EcoServ 28400 Wilber Rd. Winnie, TX 77885 409-794-3119		U.S. EPA ID Number: 39098 TXR000036731				
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
1.	Non DOT / Non RCRA Regulated	1	TT	4400	G	NHAZ1012
2.						
3.						
4.						
14. Special Handling Instructions and Additional Information: 1) Profile 1009152093BH Class 2 waste ST-5 NOT-A PO: WO 6288						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Officer's Printed/Typed Name: GARY MOORE for EPA Signature: Gary Moore Month: 12 Day: 5 Year: 14						
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name: yusef Ali' Signature: yusef ali' Month: 12 Day: 5 Year: 14 Transporter 2 Printed/Typed Name: _____ Signature: _____ Month: _____ Day: _____ Year: _____						
18. Discrepancy 18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Manifest Reference Number: _____ 18b. Alternate Facility (or Generator) U.S. EPA ID Number: _____ Facility's Phone: _____ 18c. Signature of Alternate Facility (or Generator) Month: _____ Day: _____ Year: _____						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. _____ 2. _____ 3. _____ 4. _____						
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name: _____ Signature: _____ Month: _____ Day: _____ Year: _____						

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number	
				002888838 FLE		
5. Generator's Name and Mailing Address		Generator's Site Address (if different than mailing address)				
1445 Russ Ave. STE 1200 Dallas, TX 75202-2733 214 789-1827		4904 Griggs Road Houston, TX 77021				
Generator's Phone:						
6. Transporter 1 Company Name		U.S. EPA ID Number				
Environmental Evolutions		TXR0000761218				
7. Transporter 2 Company Name		U.S. EPA ID Number				
8. Designated Facility Name and Site Address		U.S. EPA ID Number				
20400 Wilber Rd Winnie, TX 77665 409-794-3112		TXR000038731				
Facility's Phone:						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
		No.	Type			
1.	Non DOT / Non RCRA Regulated		TT	4400		NH421012
2.						
3.						
4.						
14. Special Handling Instructions and Additional Information						
11 Profile 1009152003BH 11.2 W. 6 11.22 PD WO 6288						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offor's Printed/Typed Name		Signature		Month	Day	Year
Gary Morris for EPA		[Signature]		12	5	14
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name		Signature		Month	Day	Year
Yusef Ali		[Signature]		12	5	14
Transporter 2 Printed/Typed Name		Signature		Month	Day	Year
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
Manifest Reference Number: _____						
18b. Alternate Facility (or Generator) U.S. EPA ID Number _____						
Facility's Phone: _____						
18c. Signature of Alternate Facility (or Generator) Month Day Year _____						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1.		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name		Signature		Month	Day	Year



ecoSERV

Science
beyond
compliance.

Transaction Number:	8365	Gross:	80920 lb
Transaction Date:	12/4/2014 11:00:27AM	Tare:	42040 lb
Operation:	Received	Net:	38880 lb
Account:	US EPA - REGION 6 CES	Hauler:	ENVIROMENTAL EVOLUTIONS
Contract:		Vehicle:	GREEN

Pass	Number	Pass Date	Scale Name	Weight	Manual Scale?	Operator
	1	12/4/2014 10:02:59AM	Scale 1	80920 lb	No	vicki
	2	12/4/2014 11:00:27AM	Scale 1	42040 lb	No	vicki

Material	Price	Per	Net Weight	Converted Units	Total Price
NON - HAZ BULK WATERS	0.0000	lb	38880 lb	38880 lb	\$ 0.00
				Total Amount:	\$ 0.00

Driver Signature

US DOT# 1504538
TX DOT# 006108855C
EPA ID# TXR000076018



ENVIRONMENTAL EVOLUTIONS

P.O. BOX 709 JW Rentals
ROBSTOWN, TX 78380
361-387-9400 / 877-387-9401

MANIFEST 002888838

PROJECT# _____

45160

CUSTOMER: Lone Star Ecology

P.O.#

RELEASE #

DATE: 12/4/2014

TRAILER #

VT165

TRUCK #

S016

PICKUP #

OPERATOR OR DRIVER

Yusef Ali

LABOR

GENERATOR

CES Environmental

RECEIVER

Newpark/Ecoserv

() 70 BBL VACUUM () 130 BBL VACUUM

() AUGER

() FLATBED/DROPDECK

() END DUMP () DROP DECK

() ROLL OFF

() VAN

() LTL

TIME SCHEDULE

LOADING

	MILEAGE	DATE	TIME	CIRCLE ONE
SCHEDULED ARRIVAL	<u>12</u>	<u>15-Dec</u>	<u>7:00</u>	<u>AM</u> PM
LEAVE YARD		<u>12-4</u>	<u>6:15</u>	<u>AM</u> PM
TIME ARRIVED		<u>12-4</u>	<u>7:00</u>	<u>AM</u> PM
LOADING BEGAN		<u>12-4</u>	<u>7:50</u>	<u>AM</u> PM
LOADING COMPLETED		<u>12-4</u>	<u>8:30</u>	<u>AM</u> PM

UNLOADING

	MILEAGE	DATE	TIME	CIRCLE ONE
SCHEDULED ARRIVAL		<u>4-Dec</u>		<u>AM</u> PM
TIME ARRIVED		<u>12-4</u>	<u>10:00</u>	<u>AM</u> PM
UNLOAD BEGAN		<u>12-4</u>	<u>10:40</u>	<u>AM</u> PM
UNLOAD COMPLETE		<u>12-4</u>	<u>11:00</u>	<u>AM</u> PM
ARRIVED YARD				<u>AM</u> PM

DATE	STATE NAME	ROUTES TRAVELED	MILES IN STATE (E OR I)
		<u>Pump down delayed loading</u>	
		<u>from 7:30 to 8:05.</u>	
		<u>Y.A. LSC</u>	
PICK UP: CES Environmental Site, 4904 Griggs RD, Houston, Texas; LeRoy Cassidey, 469-446-8408			
Deliver to: Newpark/Ecoserv, 26462 Wilbur RD, Winnie, TX 77665 Contact: 409-794-3455			

DESCRIPTION OF WORK: _____

COMMENTS: _____

BOX #/TRLR# DROP LOCATION

BOX #/TRLR# PICKUP LOCATION

BOX #/TRLR# RETURNED LOCATION

ENDING MILEAGE 44993.4
BEGINNING MILEAGE 44822.4
TOTAL TRIP MILES 171

SHIPPER'S SIGNATURE-CONFIRMS TIME IN PLANT

[Signature]

CONSIGNEE'S SIGNATURE-CONFIRMS TIME IN PLANT

[Signature]

DRIVER'S SIGNATURE

Yusef Ali

REVIEWED BY DISPATCH/DATE
